

ERK002 -ERK016

GENERAL INFO AND GRADING

UPSTREAM MH	DOWNSTREAM MH	DIRECTION	PIPE DIAMETER (IN)	MATERIAL	LENGTH	JOINT SPACING	ACTIVE CONNECTIONS	Structural Segment Grade	Structural Defect Total	Structural RI	Structural % Defective	OM Segment Grade	OM Defect Total	OM RI	OM % Defective
ERK002	ERK016	DS	21	VCP	340	4	4			#DIV/0!		2	1	2	

PACP DEFECT/CODING LOG

VIDEO FOOTAGE	FROM	TO	CONDITION	CODE	TYPE	GRADE	EQUILANT CONTINUOUS DEFECT	SEGMENT GRADE	COMMENTS
173.58	-	-	TAP FACTORY ACTIVE	TFA	X				Footage Appears to Have Started 173.58' Downstream of ERK002, within the Sewer
209	209	209	DEPOSITS ATTACHED ENCRUSTATION L1	DAE1	O	2	1	2	Either Deposits OR Roots, Camera Light Level obscures determination with accuracy.
243	-	-	TAP FACTORY ACTIVE	TFA	X				
245.91	-	-	TAP FACTORY ACTIVE	TFA	X				
248.08	-	-	TAP FACTORY ACTIVE	TFA	X				
337.75	-	-	SURVEY ABANDONED	MSA	X				